

68.2

Do. Long Bridge to }
top of keel }

surveyed while

R. NEWCASTLE

TELEPHONE: 21391 (3 LINES)

Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne, I.

6th September, 1949.



RECEIVED
7 SEP 1949

The Secretary,
LONDON.

ANSD.....

Dear Sir,

With reference to our Report No. 106463 forwarded today on the T.2 Tanker "HYRCANIA", we should be glad to be advised as to what fees should be charged for the Part Classification of the Hull and Machinery now carried out in addition to those detailed on the reports. In view of the nature and extent of the repairs now affected at this time, we shall be glad if you will kindly inform us what repair fee it is considered should be charged on the Hull of this vessel.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS,
per

[Signature]



© 2020

Lloyd's Register
Foundation

003631-003639-0022

003631-003631-0022

Keel
5.
midships
and }
side }
from }
side }
len. }
Area }
atling }
atling }
stem }
e line }
kness }
strake...
gard- }
ouble }
ng in }
dships in }
Wells, Angle, [or [...]
in way of Bridge, Angle, }
[or [

COM.

th and thickness at mid-line in)

Referred to Mr. Sladden.

Mr. Mellan, please.
An Moffatt



© 2020

Lloyd's Register
Foundation

OM.

FRAN
AND
FRS.
MATTI
JES
DO G
TR

68.
29.