

15th March, 1957.

LES

0, 70, 72, 76 - As recommended.

4 "CONTE BIANCAMANO" As recommended, except that a notation MBS 10,56 has been assigned.

2" 6262 As recommended, except that a notation of SS Tri. 7,56 (DR) has been assigned. It is concluded the safety valves of both boilers have been adjusted, but confirmation is desired and at the same time the pressure to which they were adjusted should be stated. Confirmation is also desired that the requirements of Circular 2032 have been complied with.



© 2020

Lloyd's Register  
Foundation