

24 JAN 1956

SHIP NAME "STAR X11" REPORT Osl. No. 7886

Existing Conditions of Class: NONE.

Endorsement of Class (B) (As before ~~xxxxxxx~~)

Condition of Present Survey: (Afloat and in dry dock)

SPECIAL SURVEY (C) due 9,55: Permanent repairs to damage caused by collision.

Recommendation: SUBMITTED record of docking 7,55 and Notation of 'ss.Dmn. 10,55' be assigned as recommended.

7,55 Dmn.
ss.Dmn. 10,55.

ENDORSEMENT OF CLASS (B).

Shell plates A.5, C.7 & E.4 (s.s.) indented.

IT IS FURTHER SUBMITTED the Surveyor be advised it is concluded there are 3 bower anchors on board but this should be confirmed.

Handwritten notes and signatures: 427/1, Lloyd's Register Foundation, 18.1.56.