

296123012

Ship's name "BRITISH GENERAL" Port ROT. No. 55054
Last survey date 8.12.62.

Class is subject to

set in shell plate G.5 (p.s.f) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~xxxxxx~~)

Nature of present survey (afloat and ~~in drydock~~)


Temporary repairs to collision damage.

Recommendation SUBJECT as above and to forecastle deck and side plating (s.s) etc. being specially examined and dealt with as necessary next drydocking.

As Now Subject.

IN S.R.L. APPENDIX

Indents in shell plates F.6 & 7 (p.s.f),
F.6 (p.s.a) and F.3 & 4 (s.s.f).



© 2021

Lloyd's Register
Foundation

Q.T.C
28/12/62
X