

Received from Chief Ship Surveyor 15 FEB 1961

SHIPS NAME "NORMAN QUEEN" REPORT Gms. No. 28584

GB

Outstanding Conditions of Class: SUBJECT to set up keel and bottom shell plating (p & s) being further examined and dealt with as necessary and to shell plates Nos. 1 & 2 (p.s.f) in 1st below sheer being permanently repaired, by the next drydocking.

S.R.L. Appendix. (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Repairs on account of collision damage - conditions of class:  
Wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 1,61' be assigned as recommended, subject to set up keel and bottom shell plating (p & s) being further examined and dealt with as necessary by the Special Survey, but without other conditions.

DS 1,61 Subject  
Without.



© 2020

*W.S.I.*  
*1-2-61*  
Lloyd's Register  
Foundation