

COPY

LLOYD'S REGISTER OF SHIPPING

Port Fremantle...W.A.20th September, 1963.

This is to Certify *that I have surveyed part of the machinery*
of the **S.S. "MULBERRY HILL"** **7121 Gross tons** of London
for **part Main Boiler Survey,**

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned.

M.B.S. 9/63 when the starboard boiler has been examined, the Safety Valves of all boilers and superheaters have been adjusted and the oil fuel burning controls have been examined.

Parts now examined:—

Port and Starboard boilers with mountings and superheaters.

P.K.L. Birk.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey	MBS Main Boiler Survey	TS Tailshaft Survey
CSM Continuous Survey of Machinery	OF Fitted for oil fuel (date) FP above 150° F.	TS(CL) Tailshaft Survey—Continuous Liner
DBS Donkey Boiler Survey	SGS Steam Generator Survey	TSN Tailshaft renewed
ES Engine Special Survey	SPS Steampipe Survey	TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert.B.1-7M-1/63-J & O'S.

003808-003815-0183

© 2020

Lloyd's Register
Foundation