

COPY

London

LLOYD'S REGISTER OF SHIPPING



Port.....CHITTAGONG,

Date.....6th July, 1963.

This is to Certify *that I have*

surveyed the **S.S. "MULBERRY HILL" 7121** *Gross tons* **of LONDON**
whilst lying afloat at Chittagong on the 21st June, 1963 and
subsequently for Damage,

and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be **retained as now classed without fresh**
record of survey subject to - Rivets at lap of plates D & E
between frames of 106 and 115 in No. 2 Hold ^{port} **being specially**
examined and dealt with as necessary at next annual Drydocking
and subject to all other outstanding items of Class being dealt
with as previously recommended."

[Signature]

(A. H. HIGNETT)
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."