

Survey fees
Docking Rs.285/-

Damage fee
Rs.50/-

Travelling Rs.20/-

EA

COPY

Ship's name

"MULBERRY HILL"

Port

Chitragong
CAL.

No.

376
342

Last survey date 4.6.63.

Class is subject to

NONE.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Docking: Damage repairs - ranging.

Recommendation

SUBMITTED record of DS 6,63 be assigned.

DS 6,63.

S.R.L. APPENDIX (AMENDED).

Lower stem bar set over to port.


Bottom shell plating slightly corrugated.

Shell plates A-5 and B.1 (p.s.a), A.4 (p.s.f)

and stern wrapper plate indented.

F.9, E.9 & 10 (s.s.amids) slightly wavy.

© 2020



Lloyd's Register
Foundation

End. S.1

003808-003815-0181

SPL FOR