

"FORT BRUNSWICK"

Abstract from endorsement on First Entry Report.

The Newport Surveyors should be informed it is concluded the shell riveting as commented upon in London Rpt. 111575 which was sent to them for their guidance, is now to be considered as being satisfactory and that no further action is necessary as regards the slightly indented shell plate G.6 (p.s.), but they should state if this is so.

See letter 22.9.44



© 2020

f.c.d.
11.9.44

Lloyd's Register
Foundation

003808-003815-0207