

found satisfactory. The material and workmanship is good. All

Empire Baffin

Await- Grk. rpt. on fitting of sea  
connections & pump-arrangements.  
X Elec. rpt. to follow. X

L.Y.  
17/10/41.



© 2020

Lloyd's Register  
Foundation

004019-004028-0111

L.Y.C. 10.41

FD S(CL)

L.Y.