

[Thin Copy for attaching to Report.]

Ltr. 4a.

LLOYD'S REGISTER OF SHIPPING

Port..... H a m b u r g

..... 24th March, 1958.

~~Dear Sirs,~~.....

..... With reference to the Survey
now being held on the

..... M.V. "WINNETOU"

I beg to inform you that, in consequence of
the condition of this vessel's ME No. 3 cylinder

jacket metalock repairs

it will be my duty to recommend to the
Committee that the same be re-examined

by September 19 58
xxxxxx (6 mos. limit)

as provided for in the Rules, an extract from
which appears on the other side:—the continuance
of the vessel's character in the Society's Register
Book to be subject to the due fulfilment of this
condition.

Yours faithfully,

B. Bräuer

.....
Engineer Surveyor to Lloyd's Register.

To.....

Messrs. Atlantic Rhederel

F. & W. Joch

HAMBURG 11, Rodingsmarkt 52