

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

28th June, 1921.

Dear Sir,

With reference to Greenock Report No. 17838 on the Steamer "CLAN MACIVER", it is concluded that the thickness of the poop and forecastle side plating and the strengthening of the sheerstrake at the ends of the bridge are all as approved, but I shall be glad if you will kindly ascertain from the Surveyors whether this is so.

I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

004206-004212-0149