

13th June, 1957.

ressel

Received from Chief Ship Surveyor **29 JUN 1957**

SHIP'S NAME "ALAVI" REPORT Bom. No. 12299

RE

Outstanding Conditions of Class: Subject to shell plate (s.s.) in way of previous sanitary discharge valve chest being dealt with by next Special Survey.

ACTION is DEFERRED for drydocking(grounding).

Alterment of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Damage repairs to indented side shell plating.

Recommendation:

SUBMITTED ACTION continues to be DEFERRED for examination in dry dock after grounding, subject as above.

As Now. Subject

IN S.R.L.  
Drydocking(grounding).



© 2020

Lloyd's Register  
Foundation

004285-004291-0110

Blk(new)

*A. Blakeman*

r Y.M.  
if on  
put c  
ds, &  
how  
if we  
letter  
No. of  
ker ..  
ate if  
gth...  
(on b  
le len  
Warps  
nd Run  
uent u  
to ren