

13 OCT 1959

Received from Chief Ship Surveyor

SHIP'S NAME "MAPLEDORE" REPORT Hfx. No. 7609
GB

Outstanding Conditions of Class:

SUBJECT to No.2 shell plate in 4th
below sheer and No.7 in 2nd below sheer (p.s.f) being specially
examined and dealt with as necessary next drydocking.

S.R.L. Appendix. (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.

Recommendation:

SUBJECT as above, but further ACTION be
DEFERRED for examination in dry dock after grounding

SUBJECT

INSERT IN S.R.L.
Drydocking(grounding).



© 2020

Lloyd's Register
Foundation

75
12/10/59