

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

Certificate of Class

Motorship "LAUST MAERSK"
Official Number - Port of Registry Copenhagen
Owners A/S D/S Svendborg and D/S af 1912 A/S (A.P.Moller, Manager)
Builders, and where and when built Odense Stalskibsvaerft A/S, Odense, January 1958.

REGISTERED TONNAGES		MOULDED DIMENSIONS	
Gross	<u>6418.68</u>	Length	<u>455' 10"</u>
Net	<u>3598.61</u>	Breadth	<u>63' 9"</u>
		Depth	<u>41' 3"</u>

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 7th January, 1958 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been **CLASSED** and entered in the REGISTER BOOK of this Society, with the Character **100A1** Carrying Oil F.P. above 150°F., Molasses, Glycerine, Vegetable Oil or Latex in Midship Tank and Deep Tanks aft subject to Periodical Surveys as required by the Rules.

(See Endorsement Overleaf)

The approved minimum freeboards from the deck line are as follows:—

Tropical	<u>1025</u>	feet	mm	inches	(T).	Winter	}	feet	inches	(WNA).
Summer	<u>1200</u>	feet	mm	inches	(S).	North Atlantic				
Winter	<u>1375</u>	feet	mm	inches	(W).	Allowance for fresh water for all freeboards	}	<u>175</u>	mm	inches

Witness my hand,

W. J. Ferguson
Secretary,


Shute
Chairman.

71, Fenchurch Street, London, E.C.3. 11th April, 1958.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society.”



Lloyd's Register
Foundation