

COPY

EA  
Ship's name

"SKOTIA"

Port

TAIPEI

No.

62-8-048

The ship is subject to Nos.1,2,3,4 & 5 'tween deck plating and adjacent structure with hatch coamings and beams also set out shell plating abreast Nos.2 & 4 hatchws (p & s) and No.1 hold (s.s.a) stringer bracket shell connection and to Nos.2,3A & 4 D.B. tank sounding pipes being specially examined and dealt with as necessary on arrival at a Japanese port via Formosa where she is now bound and by 7,62.

ACTION was DEFERRED for repairs.

The TAIPEI Surveyors report (11,62) ship examined afloat and extensive damage found resulting from faulty stowage of scrap metal cargo in Nos.1,2,4 & 5 'tween decks. Repairs were recommended but not carried out.

It would appear the ship has been sold to Formosan Ship Breakers for breaking up and the demolition was commenced 10.11.62.

A Notation of "Broken Up" was assigned 23.11.62.

R.F.C.  
10/1/63

W/S  
8/4 A



© 2021

Lloyd's Register  
Foundation