

Shaft, diameter as per ...  
as fitted

Intermediate Shafts, diameter as per ...  
as fitted

as fitted

298 1/2

Thrust Shaft, diameter as per ...  
as fitted

(Received at London Office 13 NOV 1933)

12

Place

Copenhagen

Date

6/11

19 33

We request that the Committee of Lloyd's Register will instruct  
Society's Surveyors to Specially Survey during Construction the ~~Hull~~  
~~and Boilers~~ of the Vessel No. 60 building by Messrs. 9/5  
Hskov Skibsvaerft for Messrs.

Tons. Length

Breadth

, Depth

ended to be Classed

We undertake to arrange for every facility to be given to the  
Surveyors to carry out the duty in question, and we agree to pay the fees  
the Surveyors' services, in addition to the actual travelling and other  
expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations  
Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be  
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy  
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the  
Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Engine Makers

AKTIESELSKABET

BURMEISTER & WAINSKIN- OG SKIBSBYGGERI

~~Boiler Makers~~

*[Signature]*

Secretary

Lloyd's Register of Shipping,

71, Fenchurch Street, London. E.C. (3)



004387-004393-0170

each fitted with a Discharge Valve always accessible on the plating of the vessel

yes

Are the Blow Off Cocks fitted with a spigot