

## LLOYD'S REGISTER OF SHIPPING

6266

Port ..... Yokohama .....Date ..... 8th November 1965 .....

This is to Certify that I have surveyed the **S.S. "TOSA BAY" 5217 gross tons of Hong Kong** whilst afloat at Chiba for Damage repairs to main mast and rigging, stated caused by mishandling of winch on the 3rd November 1965 at Chiba and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be **remained as now classed without fresh record of survey, subject to any outstanding conditions of class being dealt with as previously recommended.**

**H. TERASHIMA**  
Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 100m,3,64 (MADE AND PRINTED IN ENGLAND.)

004405-004410-0090