

SHIP'S NAME "SAFINA-E-JAMHOORIYAT"

PORT BAL.

No. 13007.

1<sup>st</sup> 23.6.66

LAST SURVEY DATE 21.7.66.

CLASS IS SUBJECT TO

Attached Port Bilge Pump water cylinder valve chest flange being examined & dealt with as found necessary by 3.67 (12 mos limit)

L.P. Valve faces dressed, guide adjusted & alignment checked.  
M.P. valve faces machined, side strips renewed, valve face ground, machined & liner installed, Valve cage removed & machined on face, alignment corrected, Valve rod threaded up & guide brasses renewed.

Electrical circuits generally cleared of grounds.

Stkition:- Examined P. Bilge Pump water end valve chest flange & found to remain efficient meantime.

G.E. now held for further proposed postponement over the year of 1966 & all found & placed in satisfactory condition.

ES. due 5.65 commenced 4.65 now advanced.

It is submitted that this vessel is eligible to remain as CLASSED. ES (with date) on completion of survey, Subject as above.

Submitted the proposal for postponement of SS for further period (end of September 1966) merits favourable consideration of the committee.

Owners should be informed that items examined 4.65 will require further examination for ES

© 2011  
A. 10.66.

Lloyd's Register  
Foundation