

COPY.

004426-004431-0042

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

8th August, 1950.

Dear Sirs,

T.s.m.s. "SAN PEDRO"

When this vessel was under survey at Cardiff in June last, prior to coming under survey at your port, the Surveyors stated that the oil burning system had been examined under working conditions.

In view of this statement, they were asked to state whether the outstanding items for completion of the Donkey Boiler Survey namely: adjustment of the safety valves of the oil fired boilers, had been dealt with.

In reply, they stated as follows:-

"The Chief Engineer of the vessel stated that the oil fired Donkey Boiler safety valves were adjusted at Swansea and the exhaust-heat Donkey Boiler safety valves were adjusted by the Chief Engineer at sea and were duly certified by him.

I understand that this information was reported before the case was dealt with at Barry and I regarded the Donkey Boiler Survey as having been completed for fresh record D.B.S. 10,49 as per the S.R.L.

I trust that the Chief Engineer's statement will be confirmed by Swansea Surveyors".

I shall be glad to receive your comments.

Yours faithfully,

The Surveyors,  
SWANSEA.

Clerk to the  
Classification Committee.

© 2021

Lloyd's Register  
Foundation