

"GALAXIAS"

IT IS SUBMITTED the Vizakhapatnam Surveyors be advised a certificate of fitness to be towed can be issued if they are satisfied with the condition of the ship for the proposed voyage with particular reference to bottom damage in way of No.2 D.B. tank and the remaining requirements of Instructions to Surveyors, Part 11,1954, "Towage Surveys" complied with where applicable.

The Report 10 should be headed "Seaworthy Certificate" (in relation to technical characteristics) and state the towing arrangements are the responsibility of the Owners also that the class is suspended.

*MS*

18.8.66.



© 2020

Lloyd's Register  
Foundation

004486-004488-0304