

SHIP'S NAME

APJ AMBAR

PORT

MoR

No.

98

LAST SURVEY DATE

16.1.66

CLASS IS SUBJECT TO

- ① Exhaust turbine unit not to be used until repaired & surveyed.
- ② Propeller & fastenings being specially examined at next S.O.

M.B.S. comment etc

Damage to eccentric rod & valve spindle crosshead  
burst of condenser circulating water pump engine.  
 Temp. repairs carried out but Sur recommends  
they be renewed on ship's arrival at Cochin,  
to which port now proceeding.

It is submitted that this  
 vessel is eligible to remain  
 as CLASSED. subject as now

Recommended -  
 Gas above.

© 2020

Lloyd's Register  
 Foundation