

13

MEMORANDUM

From : LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
UNITED WITH THE BRITISH CORPORATION REGISTER LONDON, E.C.3.

(Ref. F.)

To: The Surveyor(s) at HAMBURG

Date: 25.1.55.

Vessel's Name: "INDIAN ENDEAVOUR"


Question: I am in receipt of your Rpt. C.11(cont) and shall be glad if you will forward details of the new cargo hatch on casing top:-
(1) Size of hatchway, (2) Details of beams and their bearing surfaces, (3) Covers and their bearing surfaces and (4) Battening arrangements, number of tarpaulins, cleat spacing, etc. I shall also be glad to know whether a copy of this Rpt. C.11(cont) has been placed on board. J.M.

Answer:

Date: 2.2.55.

In reply to the above we would inform you that a new hatch was not fitted but the existing hatch coaming was increased in height to 900 mm, as shown on the sketch on the Rpt. C.11(cont). The size of the hatchway, therefore, the beams and battening arrangements remain the same as originally fitted. We regret the error in our report in describing the alteration carried out.

Guilther Schneider



Noted J.S. G.

5 FEB 1955



© 2020

Lloyd's Register
Foundation