

FREEBOARD REPORT on the "INDIAN ENDEAVOUR"  
HAMBURG

Submitted the Surveyor be requested to forward the following details of the new cargo hatch on casing top:-

- 1) Size of hatchways
- 2) Details of beams & their bearing surfaces.
- 3) Covers & their bearing surfaces.
- 4) Battening angles; no. of tarpaulins, cleat spacing etc.

also state whether a copy of their Rpt. CII (contd)  
has been placed on board.

J. S. H.



© 2020  
21 JAN 1955

Lloyd's Register  
Foundation