

Extract from Stam clogh 21/1/55

3570. "INDIAN ENDEAVOUR". As recommended. I shall be glad to receive your confirmation that indented shell plates No.7 from aft (port side) in 2nd and 3rd strakes below sheer, previously recorded as an endorsement (Category B), still remain to be dealt with.

Contd.



© 2020

Lloyd's Register  
Foundation

004489-004495-0156