

Received from Chief Ship Surveyor

4 APR 1961

SHIP'S NAME

"ESSO GENESEE"

REPORT

Sou.

No. 26693

ship
ed a

GB

Outstanding Conditions of Class:SUBJECT to 15 fathoms of chain
cable being supplied at the earliest opportunity.S.R.L. Appendix. (As before ~~on None~~)ature of Present Survey: (Afloat and ~~in dry dock~~)

Examination on account of leakage into No.3 cargo tank (s.s.)
and F.P.tank but no repairs were carried out as the
ship was sold to Dutch interests for scrapping.
The Surveyors, however, point out that they
understood cement boxes were fitted at the
recommendation of the M.O.T. Surveyors prior to
the ship being towed to Holland.

Recommendation:

SUBMITTED ACTION be DEFERRED pending receipt
of further information, subject as above.

SUBJECT

IN S.R.L. APPENDIX.

After bulkhead of O.F.bunker
tanks slightly bulged.

© 2021
30.3.61Lloyd's Register
Foundation's survey
have rec

Blk (new)

004603-004611-0006