

CODE  
E. GUERNSEY"  
EDITION

ESTABLISHED 1874

LOCAL AND  
TRUNK CALLS TELEPHONES

GUERNSEY  
CENTRAL 1604 (2 LINES)  
(MR. C. DOREY)  
ST. MARTIN 8939  
AFTER HOURS  
(MR. P. L. DOREY)  
ST. MARTIN 8939

DOREY & SONS,

ED  
ERS & BROKERS  
PORTERS  
HANTS

SE 1650 D.W.  
E 1410 D.W.  
T 1360 D.W.  
T 1250 D.W.  
NE 1220 D.W.  
1000 D.W.

RECEIVED

16 AUG 1957

Ans'd

CECIL DOREY, CHAIRMAN & MANAGING DIRECTOR  
PETER L. DOREY, A.I.C.S., DIRECTOR (CHARTERING)

P.O. BOX NO. 33,

GUERNSEY,

OUR REF CD/GE

YOUR REF

15th August

19 57

Register of Shipping,  
church Street, LONDON. E.C.3.

rs,

ss "PORTELET"

acknowledge receipt of yours 14th this morning.

agree this ship has not been in drydock since June, 1956.  
other hand, ship is in this port, and dries out in the  
, nearly every other week, and running repairs are carried  
and when, necessary. In fact, quite a big job was carried  
weeks back, and this next week we are arranging to deal  
ttom Ends. Vessel is perfectly tight, and making no water,  
coat the outsides as, and when, necessary, and plates just  
he bilges.

the shipping trade at the present time, as you are no doubt  
is in a shocking state. In fact, we have five ships tied  
no money available for drydocking, unless absolutely  
ry, which is not the case with this ship.

Yours faithfully,

ONESIMUS DOREY & SONS LTD.

MANAGING DIRECTOR



Lloyd's Register  
Foundation

004603-004611-0071



SR.

CLASSIFICATION

Submitted for a short time

Dr.

16.8.57

3.   
 4.   
 5.   
 6. 

10 of

YERMA

© 2021

Lloyd's Register  
Foundation

The  
star  
earl