

COPY

LLOYD'S REGISTER OF SHIPPING

NO. 715.



Port.....CHITTAGONG,.....

.....3rd April, 1965.

This is to Certify *that I have surveyed part of the machinery*
of the **S.S. "YOUSUPRAKSH"** **5975** *Gross tons* **of KARACHI**
for **advancement of MBS whilst lying afloat at Chittagong on the**
28th March, 1965, and subsequently,

and that all my recommendations have been carried out to my satisfaction. I
am reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following

survey records assigned **MBS 2.65, as previously recommended, when**
all boiler safety valves have been adjusted under steam and
the oil burning & remote controls have been examined working,
subject to wasted air heater tubes, starboard boiler, being
examined and dealt with as found necessary before the end of
June, 1965, and to any outstanding conditions of class being
Parts now examined:— **dealt with as previously recommended.**

Starboard boiler in entirety.

(A. ROSS)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CSM Continuous Survey of Machinery
 DBS Donkey Boiler Survey
 ES Engine Special Survey

MBS Main Boiler Survey
 OF Fitted for oil fuel (date) FP above 150° F.
 SGS Steam Generator Survey
 SPS Steampipe Survey

TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continuous Liner
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."