

39998

Copy to Reports [Orig 3]



CABLE IN

736

5  
COMMITTEE LDN  
OSEAGRAM 12 LN  
TX2659 TDQSA334 CDF 468 CRO218 N155  
CHITTAGONG 29 3 1640 VIA IMP

4 MAR 1965

LT  
COMMITTEE LONDONEC3

YOUSUFBKSH REURCAD REPAIRS TOBE COMPLETED IN BOMBAY  
STOP DUE TO POSTAL STRIKE EARLY RECEIPT OF NEW LOADLLINE  
CERTIFICATES UNCERTAIN STOP BOMBAY-SURVEYORSADVISED—  
~~THE~~ BOMBAY SURVEYORS ADVISED OUTSTANDING ITEMS LLOYDSREG

SENT 1209/4 MSP  
COMMITTEE LDN  
OSEAGRAM 12 LN



© 2020

Lloyd's Register  
Foundation

004642-004645-0054