



LLOYD'S REGISTER OF SHIPPING

SAFE DEPOSIT CHAMBERS
MCLEOD ROAD

KARACHI

Telephone: 30429

P. O. Box No. 4922

Cablegrams: "Lloydreg", Karachi

9th March, 1964.

Your Ref: C
DNS/DET

Dear Sir,

s.s. "YOUSUFBAKSH"

With reference to your letter of the 3rd inst., and our Report KRH/332, it is regretted that the boilers examined were incorrectly reported on the Report 9. The report should read PORT and CENTRE boilers as on the Interim Certificate, and not port and starboard. This error is much regretted.

The main engine driven pumps examined were as follows:- Air, feed (2), bilge, and sanitary pump with all links and levers. *2 pumps*

It is regretted that this was not made clear on our report.

I am, Dear Sir,
Yours faithfully,

T.L. Palmer
(T.L. Palmer)
For The Surveyors.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

004642-004645-0088

ER

DATE

ORT

1/11

YS WRH 21-2 SS

R 10/3/64



© 2020

Lloyd's Register
Foundation