



# BAP LLOYD'S REGISTER OF SHIPPING

London and District Surveyors' Office

Barclays Bank Chambers, 1, Minories, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: Royal 3801, 3802, 3803  
Telex No.: 24305

Please address  
further communications  
on this subject to  
THE SURVEYORS

15th June, 1964.

Dear Sir,

I forward herewith, for your attention, the following drawings giving details of the screw shafts for the following ships of The New Zealand Shipping Company, Limited.

Drawing No. 610

PAPANUI	BUILT 1943-6	TSCL 7.63
PAPAROA	" 1944-1	TSCL 9.63
PIPIRIKI 8-6	" 1944-5	TSCL 6.63

Drawing No. 295

DEVON	BUILT 1946-2	TSCL 8.62
DORSET	" 1949-11	TSCL 2.62

Drawing No. 949

GLOUCESTER	BUILT 1941-7	TSCL 10.62
------------	--------------	------------

Drawing No. 1999

NOTTINGHAM	BUILT 1950-6	TSCL 10.62
------------	--------------	------------

Drawing No. 4977

NORTHUMBERLAND	BUILT 1955-5	TSCL 6.61
MIDDLESEX	" 1953-4	TSCL 7.63

Drawing No. 5336

WHANGAROA	BUILT 1955-10	TSCL 10.61
WHAIFANUI	" 1956-9	TSCL 5.61

Drawing No. 4343

ESSEX	BUILT 1954-5	TSCL 7.63(N)
OTAKI	" 1953-5	TSCL 8.61(N)

Drawing No. 5926.

TURAKINA	BUILT 1960-9	TSCL 9.63
----------	--------------	-----------

Drawing No. 5054.

SOMERSET	BUILT 1962-11	TSCL 11.62
PIAKO	" 1962-1	TSCL 1.62

Will you please state if these shafts conform to C1002 and if so when the surveys become due.

Please return the plans with your reply.

Yours faithfully,

© 2020  
Lloyd's Register  
Foundation  
Principal Surveyor.

004653-004661-0202



GLOUCESTER

Screwshaft (CL) 18" Dia.  
Round key - Root radius  
not shown on plan.

Root rad as for "Dorset" which approved

Not crack detected last survey in 10.62

Keyway particulars in accordance with  
CL002 and provided shaft is crack  
detected next TS due 10.65 it  
will be in order for subsequent  
Screwshaft Surveys to be  
held at intervals of  
4 yrs.

*[Signature]*

19.6.64

SRL (MPP)  
Noted in SRL (MPP)  
16.11.64

*[Signature]*



© 2020

Lloyd's Register  
Foundation