

22 AUG 1964

O  
COMMITTEE LDN  
OSEAGRAM 19 LN

CABLE IN

RECEIVED

801  
5 - AUG 1964

Ans.....

TX0542 TNA71/1775  
RIODEJANEIRO 56 4 1440 LT =  
LT COMMITTEE LONDONEC3

SALAMMANNA SURVEYOR OUT OF PORT STOP IN VIEW OUR REPORT 9602  
RECOMMEND KINGSTON SURVEYOR SATISFIES HIMSELF SHIP FIT TO  
PROCEED EUROPE STOP NOTE OWNERS STATED CARGO DESITINED  
TRINIDAD AND USA WHEN INTERNAL EXAMINATION COULD HAVE BEEEN  
CARRIED OUT STOP NOTE ALSO PORT BOILER STARBOARD FURNACE  
CONDITION THREE INCH DEFORMATION OF E E E DEFORMATION ON  
THIRD CORRUGATION  
SURVEYOR +

CLONDONEC3 9602 +

COMMITTEE LDN  
OSEAGRAM 19 LN  
SENT 0538/5 HN



© 2021

Lloyd's Register  
Foundation

604698-004702-0109

REPORTS

*gph*

*Consider further examination  
before purchase required at Kingston  
less. 5.8.64*



© 2021

Lloyd's Register  
Foundation