

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

Your Ref: NSV/KP

13th July, 1964.

C  
RLT/CB

Dear Sirs,

Steamer "SALAMMANNA"

With reference to our recent correspondence concerning this ship, a Report from the Society's Surveyors at Rio de Janeiro has now received the consideration of the Committee.


The Surveyor has recommended that permanent repairs to buckled and set up stem, keel and bottom plating etc. (port and starboard) in way of fore peak, Nos.1 and 2 double bottom tanks be specially examined and dealt with on completion of the present voyage to the U.S.A. and also that the starboard furnace of the port boiler be repaired or renewed by the end of this month. Meanwhile class has been continued subject, inter alia, to these matters receiving attention as recommended and I shall be glad to know what arrangements have been made regarding these items.

It is understood from the Rio de Janeiro Surveyors that the Special Survey will be held on completion of the present voyage and I shall be glad if you will advise me as soon as possible when and where this will take place.

Yours faithfully,

Deputy Clerk to the  
Classification Committee.

Messrs. N. & J. Vlassopoulos Ltd.,  
Bevis Marks House,  
Bevis Marks,  
LONDON, E.C.3.



Lloyd's Register  
Foundation

004698-004702-0115