



اللـوـيـدز رـيـجـسـتـر أـوـف شـيـبـنـج

LLOYD'S REGISTER OF SHIPPING

"Antoun Turks" Building
15, Gohar Al Kaid Street
P. O. Box 68
Port-Tewfik
Telephone No. 3671 Suez
Telegrams: Lloydsreg.Suez

عمارة أنطون تورك
١٥ شارع القائد جوهر
ص. ب. رقم ٦٨
بورتوفيك
تليفون رقم ٣٦٧١ السويس
العنوان التلغرافي: لويذرريج-السويس

Reference

C

RECEIVED
12 AUG 1963

31st July, 1963.

Dear Sir,

S/S "SALAMMANNA"

W^r refer to Middlesbrough letter dated 19th June, 1963 reference PBC/MAM/A-Z(S) and c.c. Secretary London.

The repairs have been carried out in accordance with the contents of this letter as shown in our report No. 1892.

The Annual Load Line Survey has now been carried out and the Certificate endorsed on the 28th July, 1963.

The master stated that the condition concerning the life boats' provisions has been dealt with at Bayonne and a Surveyor attended to it. He also stated that the other condition of the Safety Equipment Certificate regarding the defective lead of the emergency fire pump would be dealt with at the next drydocking.

Yours faithfully,

G. Copty
SURVEYOR.

The Secretary.,
LONDON.

SUEZ 138



© 2021

Lloyd's Register
Foundation

004698 - 004702 - 0138

