


COPY

of Rm No 60913

LLOYD'S REGISTER OF SHIPPING



Port CARDIFF

Date 12th August, 1959

This is to Certify *that I have*

Surveyed the s.s. "HOLDERNOCK", 981 tons gross of Hull, whilst
afloat at Cardiff on the 7th August, 1959 and subsequently on
account of damage stated to have been sustained when vessel
came in contact with quay wall on entering Cardiff Docks on
the 7th June, 1959,

*and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will*
Recommend *that she be* continued as at present classed in the

Register Book, without fresh record of survey, subject to
permanent repairs to the damaged stem and plating being carried
out before the end of October 1959, and to all other outstanding
items being dealt with as previously recommended.

(A. Jackson)

Jackson
Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 100m,4,59

(MADE AND PRINTED IN ENGLAND.)

004769-004777-0164