


COPY

# LLOYD'S REGISTER OF SHIPPING



No. LSA-745

Port Yokohama

14th March, 1966

✓ R-

This is to Certify that

H. TERASHIMA

the undersigned Surveyor to this Society did at the request of Messrs. Cornes & Co., Ltd., Lloyd's Agents, Yokohama, on behalf of the Salvage Association, London and with the consent of the Master, attend on board the M.S. "RION" 10,984 tons gross of Piraeus, whilst the vessel lay afloat at Tokyo on the 8th March 1966 for the purpose of ascertaining the nature and extent of Damage stated cause unknown on the 9th February 1966 at Singapore.

For further particulars please see the ship's log books.

In the opinion of the undersigned the damage found was reasonably attributable to the alleged cause and recommendations for the repairs as stated below were made without prejudice to the terms and conditions of insurance.

Found

1. Starboard bower anchor missing.
2. 15 fathoms chain cable missing.

Recommended


1. To renew.
2. To renew.

Recommendations for the repairs as stated above including the necessary staging, removal and replacement of parts for access and painting of new and disturbed work were made with a view to placing the vessel in a similar condition to that which prevailed prior to the alleged casualty.

Repair for item 1 as recommended was carried out in the satisfaction of the undersigned by Niko Ship Repairing Co., Ltd., Yokohama (Spare anchor on board used) at a total cost of ¥ 192,900.- (Yen One Hundred Ninety Two Thousand and Nine Hundred only) which price is considered reasonable for prevailing costs in Japan.

Repair for item 2 was deferred to the Owner's convenience time.

The repair was commenced and completed on the 8th March 1966.

  
SURVEYOR TO LLOYD'S REGISTER  
OF SHIPPING

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."

(Rpt. 10) 8,65 KOB

004789-004798-0216