

7 AUG 1964

Ship's name DURHAM

Port Durban

No. 10884

Class is subject to

Last survey date 24/6/64

P.A. aux. engine scavenge pump bottle  
guide jacket (Matalock S.63) beins  
examined by S.65.

Nº3 unit starb'd m.e piston cooling  
& L.O. system repairs carried out  
by ship's staff now permanently  
repaired

*It is submitted that this  
vessel is to remain  
as CLASSED.*

subject

to above

© 2020

Lloyd's Register  
Foundation

5/8/64