

Rpt. 8

Date of writing Report

Survey held at

When handed in at Local Office

Port

No.

Received London

No. of Visits

First Date

Last Date

# REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

on the Iron or Steel S.S.

Built at

By Whom

Tons gross

Year

Month

Owners

Owners' address  
(If not already in R.B.)

Managers

Port of Registry

Surveyed Afloat or in Drydock

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

Port

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

SHIP'S CLASS

Date of Special and of Drydocking Surveys, etc.

Machinery

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft

ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

Has a Survey also been held on machinery of the Ship?

If so, is the Report sent now, or when will it be sent?

Is Classification Certificate required? If so, to be sent to

Has Interim Certificate been issued?

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

Surveyor to Lloyd's Register of Shipping

Date of Committee

FRIDAY 24 AUG 1962

Minute

Write Adm

Class withdrawn

20m,4,61 T. (MADE AND PRINTED IN ENGLAND)

GENERAL COMMITTEE

Thursday 11 October 1962  
Classing Committee's decision confirmed.

© 2020

Lloyd's Register Foundation