

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

14th January, 1966.

R
SEI/CB

Dear Sirs,

S.S. "MANSOOR"

In reply to your letter of the 5th January I have to say that in view of the vessel's age no postponement of the Special Survey can be contemplated unless a full and satisfactory General Examination of the hull and machinery is held in drydock now. This General Examination must include the internal examination of any water ballast deep tanks and the testing of the bilge suctions.

There will be no objection to the repairs in respect of the hull condition of class being deferred provided you are satisfied with the efficiency of the items for the period of postponement desired. It will, however, be necessary for the machinery conditions of class, requiring the propeller to be specially examined and dealt with and the starboard boiler centre furnace back tube plate etc., to be examined and dealt with on arrival at Karachi, to receive attention at the present time.

On receipt of a satisfactory Report on the above the Committee will then be prepared to consider the postponement of the Special Survey until some time before the end of January, 1967.

It is concluded that the Main Boiler Survey due at the end of the present month will be held at this time.



© 2020

Lloyd's Register
Contd.
Foundation

004887-004892-0243 1/2

- 2 -

I would remind you that a Steampipe
Survey will be required by the completion
of the Special Survey.

Yours faithfully,

e.c. FBD

Assistant Clerk to the
Classification Committee.

The Surveyors,
KARACHI.



© 2020

Lloyd's Register
Foundation

0243 2/2