

Ship's name

"WAPFU"

Port

HFS

10 OCT 1963

No. 743

Last survey date 30.7.63

Class is subject to

Metallock repairs to Main engine LP cast iron column under pump lever bracket being specially examined before end of January 1964 (12 months limit).

Docking, wear down 3.2 mm.

MBS due 6.63 now held.

SRL item: Main engine LP cast iron column under pump lever bracket now specially examined and found efficient and Surveyor recommends that this item be deleted from SRL, but a suitable note made in SRL appendix.

General Examination in accordance with Circular 1959 carried out at this time for proposed postponement of Special Survey and all found satisfactory.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh record of MBS 7.63 now without special conditions.

SRL appendix to note:

Main engine LP cast iron column under pump lever bracket Metallock repaired.