

Ship's name "KAVO MARAPAS"

Port

Bbo

No.

13939

Last survey date

16.3.65

Class is subject to

NONE

IT IS FURTHER SUBMITTED THE SURVEYORS  
IN THIS AND FUTURE SIMILAR CASES SHOULD REPORT  
THE ALTERATIONS FOR INCREASE IN DRAFT ON  
THE REPORT AS IT SHOULD BE A COMPLETE DOCUMENT  
IN ITSELF AND IT IS NOT SUFFICIENT TO REFER  
S.R.L. Appendix (as before ~~XXXXXXXX~~) II.3 of  
Nature of present survey (afloat and in drydock)

Docking: Damage repairs (contact).  
Stiffening for deeper loading in accordance with  
Secretary's letters.

Recommendation

SUBMITTED record of 'DS 3,65' be assigned.

DS 3,65.

IN S.R.L. APPENDIX

Shell plate G.10 (s.s. from fwd) indented.  
AMEND RB.



FROM:- Mid.L. 360'-0" TO:- 360'-5"

DELETE - OSD.

INSERT - 2 dks.

NOTED FOR  
POSTING

18.8.65  
C.G.B.



Lloyd's Register  
Foundation

P.T.O.

13933

Boo

Ship's name "KAVO MARAPAS"

18.3.65

Date survey done

None

IT IS FURTHER SUBMITTED the Surveyors  
 in this and future similar cases should report  
 the alterations for increase in draft on  
 the Rpt.8 as it should be a complete document  
 in itself and it is not sufficient to refer  
 to C.11(contd.)

*4/19/65*

*THIS*

*Billboard on 2/15/65*

Stiffening for deeper loading in accordance with  
 Secretary's letters.  
 Docking: Damage repairs (contact)

SUBMITTED record of '08 & '65' be assigned.

DA 3,65.

APPENDIX

Shell plate 2.10 (e.a. from fwd) indented.

FROM: Mid. L. 251-0" TO: -- 360'-5"

DEBATE - OGD.  
 W. 2. Dks.

P.T.O.



2020  
 Lloyd's Register  
 Foundation