

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



305/60

Port Helsingfors,31st October, 1960.

This is to Certify that I have

ps-/

Surveyed the Boiler ~~and Machinery~~ of the S.S. "HEKTOS" at  
Teppila, 22-24.10.60, whereby the safety valves of this  
Boiler also were adjusted under steam,

and that I have transmitted to the Committee of Lloyd's  
 Register of Shipping, London, a Report stating that all  
 recommendations made by me in connection therewith have  
 been carried out to my satisfaction, and that I have  
 Recommended that the record of \_\_\_\_\_

MBS 10/60

be made in the Register Book in the case of this vessel when  
 the survey has been completed.

~~Parts now examined:~~

To complete the Boiler Survey the ss-Boiler to be surveyed.

  
 A. Weber.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member of, or the Surveyors, or other Officers or Agents of the Society."