

14 APR 1957

Received from Chief Ship Surveyor

S NAME "MOUNT OLYMPUS" REPORT Pir. No. 7095

anding Conditions of Class: Subject to permanent repairs to breast
hook plating at top of lower fore peak space and A.P. bulkhead in way
of tunnel well by the Special Survey, and to rudder mainpiece
(E.W. & reinforced 6,56 & previously) being specially examined next
drydocking.

sement of Class (B) (As before ~~XXXXXX~~)

ys due: SPECIAL SURVEY (C) due 7,56. Postponement until 1,57
approved 24.7.56.

e of Present Survey: (Afloat and in dry dock)

Docking: Special Survey:

Wear and tear repairs and to part of the deferred items as above:
Alterations to deep tank in accordance with approved plan.

1 Features:

erim Certificate in order (Yes-No-None)

Outstanding: (If any for S.S. or A.S.)

NONE.

be completed ~~xxxx~~

ndation:

SUBMITTED record of docking 1,57 and Notation
of 'ss.Pir. 1,57' be assigned, subject to rudder
mainpiece (E.W. & reinforced 6,56 & E.W. previously)
being specially examined next drydocking, without
other conditions but with Endorsement (B).

(1,57 Pir. Subject
Without.
(ss.Pir.1,57.

IT IS FURTHER SUBMITTED the Surveyors in this and
future similar cases be requested to furnish the approved plans
indicating the alterations effected.

ENDORSEMENT OF CLASS (B).

Bottom plating (s.s.a.) and shell plates F.3 & 4, G.2, 3 & 4 and
H.6 (s.s.f.) slightly indented.

Blk(new)

S.A.F.

Second Surveyor's Fee (if any)

Stamps

7 0 0

WEDNESDAY 9 APR 1957

Surveyor to Lloyd's Register

005013-005019-0156

© 2021

Lloyd's Register
Foundation