

2m,9,60

(a) Class is subject to the main MP valve chest METALOCK repairs being specially examined at the next Special Survey. (b) The main H.P. guide shoe being removed at a Persian Gulf port Feb., 61. 4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 14 APR 1961

SHIP'S NAME "MARGALANTE II"

REPORT KHORRAMSHAHR No. 308.

S.R.L. Item (b) regarding the main engine H.P. guide shoe now dealt with and the Surveyor recommends that it be deleted from the list.

It is submitted that this vessel is eligible to remain as **CLASSED**. Subject to item (a) being continued but without special condition regarding the main H.P. guide shoe.

Lloyd's Register
Foundation

005069-005074-0119