

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Hoordam

Rpt.

Rot. No. 27376

Ans. No. 15-128

Ch. 10429


25131

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Pie Engines 2 S.C.S.A.
24 G. 24 7/8" - 45 1/4"



2482 N.A.P.

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of
 approved type

Yes
No

This vessel's machinery appears to have been built in accordance
 with the Rules and the approved plans, and it is submitted she is
 eligible to be classed *+LMC 9.38*

2 DB 100 lb.

L.Y.
14/10/38



© 2020

Lloyd's Register
 Foundation

005107-005117-0158