

27909

2. FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Name Attivita 44 War Column
No. in Reg. Book 33878 W. Supp
Registry (For Foreign Vessels) Savona
Steel State whether Classed by Lloyd's Register Yes
of Owners Date of Verification

I have to report that the Freeboard from the centre of disc to the top of the dry deck line, and the lines in connection therewith, as given below, assigned to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:--

From centre of disc to top of statutory deck line 5 ft. 11 1/2 ins.
From centre of disc to top of statutory deck line at awning or part-awning deck . . . . . ft. ins.
Fresh water line above centre of disc . . . . . 6 ins.
Indian Summer line above centre of disc . . . . . 5 1/2 ins.
Winter line below centre of disc . . . . . 5 ins.
Winter North Atlantic line below centre of disc . . . . . ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side } at main, spar or upper dk. 13/4 ins.
} at awning or pt.-awning dk. ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

Certs to have

GRM 10.3.20

Surveyor.

(To be filled up in London Office.)

Document No. Date of Committee's Minute
Added Depth for record . . . . . ft. ins.
Freeboards compared and found correct by date
Fee paid? Form for Certificate A
Instructions date
Certificate written 10.3.20 Noted for posting



© 2020

Lloyd's Register Foundation

005132-005140-0285