



Referencia

LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3.

Edificio San Esteban, Gijón

6th August 1964

Telegramas: Register

RECEIVED

12 AUG 1964

Teléfono 4-95-15

Dear Sir,

"ECLO"

Further to your letter of 28th July 1964, we confirm that spaces under the boilers were examined and found satisfactory, safety valves of all boilers adjusted and set at a pressure of 225 p.s.i.

Yours faithfully,

G. J. Munkle

p.p. The Surveyors,

The Secretary,
LONDON.-



Lloyd's Register
Foundation

005180-005186-0238

SR

REPORTS

mm

mm

mm
14 AUG 1964



© 2020

Lloyd's Register
Foundation