

-4. MAY 1966

Ship's Name ~~SS~~/MS "PHOENICIAN STAR"
 Gross tons 4,982 Port of Registry Panama Port Hakodate
 Date of build 5/36 Is there a Rpt. 9? No Rpt. No. H-1137
 No. of visits 1 First date - Last date 7-4-66
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) YKA 6539
 Date of completing rpt. 9-4-66 Surveyed at, if different from Port above Muroran
 Surveyed afloat and/or in D.D. afloat Last date of examination in D.D. -
 Has a Load Line Survey been held? No Summer freeboard as verified -

State which additional Rpt. 8 is attached: (Cont) / (PS) / (DP) / (EQ) / (Rig) /

Survey fees D.S. - £ 14- 0- 0
 Damage fee
 Expenses £ 6- 0- 0
 S.A. fee £ 6- 0- 0

I have surveyed the above-named ship in accordance with the Rules for Shell leakage.

Stern cant shell (p. side) G-1 in store space holed and generally wasted. Temporary repair by fitting E.W. doublers inside effected and permanent repair has been recommended to carry out at next drydocking.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~xxx~~ with/without fresh record of dry docking subject to stern cant shell (port side) holed now temporarily repaired being permanently repaired at next drydocking and to any condition at present attached to class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

K. Ikehata
Surveyor to Lloyd's Register of Shipping

FRIDAY 13 MAY 1966

Deferred for SS (by 8.66)
(subject to...)
ABS 166

note YKA use subj(?)
& Cick christ own.

ALSO FOR

SPL FOR

POSTING

HEADER

FOR CHAIRMAN CLASSN. CTTEE CERT

STAMP: PROCEEDING RECORDS SHIP

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due