

26 JUL 1965

Ship's name "PHOENICIAN STAR"

Port YKA

No. 5989

Class is subject to NIL

Last survey date 5.6.65.

CSN advanced. TSCC. (due 8/64) now held. Repairs

Searchlight found to be in accordance with C1102.
having been work-detected or repaired.

It is submitted that this
vessel is eligible for THE
RECORD TSCC 5/65.

Inform owner
re searchlight.

(8)
S.R.L. - Appendix Note
TSCC 7.1.66

23/7/65.

It is not examined for 4 yrs:-

main engine Nos. 2 and 3 centre + side top and bottom
ends and bearings.

Nos. 1, 3 + 4 main journals + bearings.

Holding-down bolts + checks.

& to complete the CSN (due 8/65):-

Examine above items and

Belge pump, Thrust + intermediate shafts

and bearings, machinery trunks, main fuel injection

pumps, Belge pump, lubricating - oil cooler.

Pumping arrangements, starting - air pipes, evaporator

oil fuel tanks, Boiler OT. pressure pumps, Belge

air-receivers, steering machinery, Inboard air-compressor, etc.

steam dynamo engines, electrical installation.

WD 1.27m.
(Rwood @ 4.37)

© 2020

Lloyd's Register
Foundation

158