

Ship's Name ~~XXMS~~ 'SAN FERNANDO' Gross tons 4925
Is there a rpt. 8? Yes Port Colombo Rpt. No. 5806
No. of visits First date Last date
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)
Date of completing rpt. 26.1.65 Surveyed at, if different from Port above
Is a rpt. 9A attached? Yes MN (388) Nature of survey
Survey fees Damage fee Expenses
S.A. fee

DOCKING
Propeller Sea connections Oil gland
Fastenings Wear down of stern bush
Has screw/tube shaft been drawn? Date of examn.
Has shaft been changed? Has shaft now fitted been previously used?
Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN
Upper O.F. & E.G. Good; 4.11.64
Lower O.F. Good; 1.12.64

Air heaters Good
Superheaters -
Safety valves Good
Mountings, doors and fastenings Good
Safety valves { Sat 120 P.S.I.
adjusted to { Spt -
Boiler securing arrangements Good

Main economisers - Exhaust gas heated economisers -
Steam heated steam generators - Steam generator safety valves adjusted to -
Forced circulating pumps - Funnel Good
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? - Were oil burning system & remote controls examined in accordance with rules? Yes

I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

Surveyor to Lloyd's Register of Shipping

(B. Borkett)

TUESDAY 23 MAR 1965

See Rpt 9A

Lloyd's Register
Foundation

ALSO FOR

SPL FOR

NOTED BY
CESR
SRL

POSTING

HEADER

CERT

005187-005193-0311

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is